

CMA Closure Specifications

| Closure Size | T | | T1 | E | | E1 | H | |
|--------------|-------|-------|-------|-------|-------|-------|------|------|
| | Min. | Max. | Max. | Min. | Max. | Max. | Min. | Max. |
| 24-410 | .941 | .955 | .964 | .857 | .871 | .880 | .622 | .652 |
| 28-400 | 1.089 | 1.103 | 1.110 | .995 | 1.009 | 1.016 | .388 | .406 |
| 38-400 | 1.47 | 1.49 | 1.498 | 1.383 | 1.397 | 1.404 | .388 | .406 |
| 38-430 | 1.477 | 1.491 | 1.498 | 1.383 | 1.397 | 1.404 | .941 | .959 |
| 48-400 | 1.871 | 1.885 | 1.892 | 1.777 | 1.791 | 1.798 | .388 | .406 |
| 48-485 | 1.871 | 1.885 | 1.892 | 1.777 | 1.791 | 1.798 | .406 | .424 |
| 53-400 | 2.068 | 2.082 | 2.089 | 1.974 | 1.988 | 1.995 | .401 | .419 |
| 53-485 | 2.068 | 2.082 | 2.089 | 1.974 | 1.988 | 1.995 | .401 | .419 |
| 63-485 | 2.462 | 2.476 | 2.483 | 2.368 | 2.383 | 2.389 | .401 | .419 |
| 89-400 | 3.512 | 3.528 | 3.537 | 3.392 | 3.408 | 3.417 | .515 | .595 |
| 110-400 | 4.322 | 4.350 | 4.360 | 4.212 | 4.230 | 4.240 | .577 | .595 |

The "T" and "E" dimensions measured at the top of the closure at a practical point near the end of a full thread.

Closure specifications taken from The Closure Manufacturers Association's (CMA) technical website.

For more information, contact your Account Representative.
610-367-5000